

## RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080007-6

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPEN NUMBER	BUY OUT CODE NO.	O. ACCT. OR W.O. NO.	R. S.O. NO.	REMARKS
QUANTITY RECEIVED	322	000000	12138	0 0	00	00	00				

DRAWING NO. AND DESCRIPTION

12 731267-1 ROCKLER CLUTCH

SHIP M/MC 85840

TO SUPERSEED 731267 128114

*W.E. Johnson*

RECEIVED BY

HMC-1069

INSPECTED BY

QMA

DATE

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11024

CHARGE TO  
QUANTITY RECEIVED

DATE REC'D.

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPEN NUMBER	BUY OUT CODE NO.	O. ACCT. OR W.O. NO.	R. S.O. NO.	REMARKS
QUANTITY RECEIVED	322	000000	12138	0 0	00	00	00				

DRAWING NO. AND DESCRIPTION

12 731267-2 ROCKLER CLUTCH

SHIP M/MC 85840

TO SUPERSEED 128115

*W.E. Johnson*

RECEIVED BY

HMC-1069

INSPECTED BY

QMA

DATE

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080007-6